

SPESIFIKASI TEKNIS
PENGADAAN WINDSHIELD PESAWAT UDARA BALAI BESAR KALIBRASI FASILITAS PENERBANGAN
TAHUN ANGGARAN 2023

NO.	NAMA BARANG	PART NUMBER	JUMLAH	KETERANGAN
1	2	3	4	5
1	Panel Assy - Windscreen A, RH	NF24016-416	1 Ea	
2	Panel B Window, RH	NH24016-92	1 Ea	
3	Windshield Assy-LH Heated	101-384025-23	1 Ea	
4	Windshield Assy-RH Heated	101-384025-24	1 Ea	
5	Screw	MS24694-S61	145 Ea	
6	Strip-Sponge Rubber Top	50-420066-351	3 Ea	
7	Seal Silicon Top	50-420066-345	3 Ea	
8	Strip-Sponge Rubber Outb/Center	50-420066-347	6 Ea	
9	Seal Silicon Outb/Center	50-420066-341	6 Ea	
10	Strip Sponge Rubber Bottom	50-420066-349	3 Ea	
11	Seal Silicone Bottom	50-420066-343	3 Ea	
12	Nutplate	MS21061L3	20 Ea	
13	Sealant	PR1425 B1/2	8 Can	
14	Sealant	PR1422 B2	2 Can	
15	Sealant	PR1440 C20	4 Semkit	
16	Promoter	PR142	1 Ea	
17	Adhesive	Loctite 270	1 Ea	
18	Adhesive	Loctite 271	1 Ea	
19	Adhesive, Silicone	SRC18 or SR529	2 Ea	
20	Cleaner Solvent	MIL-PRF-680B	1 Can	
21	Methyl Propyl Ketone	SPC 19010	1 Gal. Can	
22	Cement Silicon	Dapco 3300	2 Pint Kit	
23	Adhesive	EC-1300L	1 Can	
24	Urethane Paint Stripper	Turco 6776 or Turco 6813	1 Pail	
25	Epoxy Primer (High Solid)	MIL-PRF-23377	2 Gal. Kit	

Tangerang, 7 Juli 2023

Pejabat Pembuat Komitmen

Balai Besar kalibrasi fasilitas Penerbangan



PRAYUDI

NIP. 19761226 199803 1 002